



REVISION HISTORY

REV	DESCRIPTION	DATE	APPROVED




Top View

TANK IS CALIBRATED
IN 50 GAL INCREMENTS



ISO View



Side View

wall thickness: 0.350"

 16160 Hwy 27 Lake Wales, FL 33859																	
<table border="1"> <thead> <tr> <th> </th> <th>NAME</th> <th>DATE</th> </tr> </thead> <tbody> <tr> <td>DRAWN</td> <td>mnegron</td> <td>9/7/2007</td> </tr> <tr> <td>CHECKED</td> <td> </td> <td> </td> </tr> <tr> <td>ENG APPR</td> <td> </td> <td> </td> </tr> <tr> <td>MGR APPR</td> <td> </td> <td> </td> </tr> </tbody> </table>		NAME	DATE	DRAWN	mnegron	9/7/2007	CHECKED			ENG APPR			MGR APPR			TITLE V-700 Gallon Tank	
	NAME	DATE															
DRAWN	mnegron	9/7/2007															
CHECKED																	
ENG APPR																	
MGR APPR																	
SIZE A	MATERIAL: LMDPE	REV															
FILE NAME: V-700 Vertical.dft																	
PART#: 900700	WEIGHT: Error: No referenc	SHEET 1 OF 1															

UNLESS OTHERWISE SPECIFIED
DIMENSIONS ARE IN INCHES
ANGLES ±0.5°
2 PL ±0.125" 3 PL ±0.060"